

GENERAL SERVICES ADMINISTRATION

Sample Numbers: 94244565 - 94244574.

EPA REGION 10 PROJECT REQUEST FORM

Project Name: <u>Nudelman & Sons; Portland, OR.</u>
Project Code: <u>OOO-054B</u>. Account Code: <u>AI</u> Account Code: AFLL3A.

Analyses Requested:

Parameter or		Quantitation	# 1262	
group of compounds PCBs:	Method As per PCB OAPjP.	limits 1 ppm.	S W	TRIX Other 1 wipe
H H	n n	1 ppm. 1 ppm.	1	3 debris
Sampling Date(s): 6	/13/94. Shipping Da	ate(s): 6/17/94.		
Project Officer: Da 6869/(206)553-7369.	n Heister(000)/Bill	Hedgebeth (ATD) .	Phone #_(503) 326-
Has this project be	en previously reques	sted? yes; only	verbably	<u>-</u>
If so, on what date				
suspected of illega PCB regulated equipa taken place. Samplia reporting a fire at	for QA/QC and delive lly storing PCB transment on premises. QA ng was initiated from the site which may collected by D. Heist	nsformers, capac APjP was submitt om a phone call have involved P	itors and ed after s	other TSCA sampling had
Requested by: Arthu	ur Dan Baker, III; OA	Management Off	ice; Seatt	le, WA.
Date: _6-17-94.				
Accepted Parameters:	BELOW FOR LAI	per Bub	2 4/1	7/94 Ky
Rejected Parameters:	Shorto.			
te jested Tarameters.	-11000			
Comments:				
insmitted by Lat	Escire Gra Kl	OCF Date:	6/n/94	
HIS FORM MUST BE FA AB FAX #: (206)895-	ARD TO THE LAB BEFORM		TILL BE AP	PROVED.
		RANSMITTAL	# of pages ► 3	
	Degy/Agency	ork; From Arth ERA Reg	IN RA LAB ; SE	المراجعة الم
	Deglingency Manches	Ter Lap. (3	206)553-1	692